	Туре	L #	Hits	Search Text	DBs		Time Stamp	lime tamp	Time C
Р	BRS	L1		(ferrule and (((press or friction) near2 fit) or (friction near3 force)) and bore and housing and (split adj sleeve)).clm.		r2 re US-PGPUB		US-PGPUB 0	US-PGPUB 0

(interference)